



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
SWALEDAL ROAD	opp 12	Damaging	Kerbs missing, cannot install - completely unable to root prune, work round/reinstate: buttresses in carriageway.	Platanus x hispanica	Plant in new 800mm pit opp12 (same as felled tree)	Acer campestre 'Elegant'
SWALEDAL ROAD	o/s 6	Damaging	F/W uplifted and kerbs displaced by roots - likely to be damaged upon reconstruction	Platanus x hispanica	Plant in new 800mm pit opp 6-8 (opp felled tree)	Acer campestre 'Elegant'
SWALEDAL ROAD	o/s 24	Damaging	Kerbs absent, unable to install/repair without sever root damage	Platanus x hispanica	Plant in new 800mm pit opp 24 (opp felled tree)	Acer campestre 'Elegant'
SWALEDAL ROAD	o/s 5	Damaging	Kerbs absent, unable to install/repair without sever root damage	Platanus x hispanica	Plant in new 800mm o/s 5 (same as felled tree)	Acer campestre 'Elegant'
SWALEDAL ROAD	o/s 11	Damaging	Extensive f/w damage, growing within c/w - no kerbstones	Platanus x hispanica	Plant in new 800mm o/s 11 (same as felled tree)	Acer campestre 'Elegant'
SWALEDAL ROAD	o/s 29	Damaging	Extensive f/w damage, growing within c/w - no kerbstones	Platanus x hispanica	Plant in new 800mm o/s 29 (same as felled tree)	Acer campestre 'Elegant'
SWALEDAL ROAD	o/s 52a	Damaging	Extensive f/w damage, growing within c/w - no kerbstones	Platanus x hispanica	Plant in new 800mm o/s 52a (same as felled tree)	Acer campestre 'Elegant'
SWALEDAL ROAD	o/s 50	Damaging	Extensive f/w damage, growing within c/w - no kerbstones	Platanus x hispanica	Plant in new 800mm o/s 50-52 (repositioned to between 2 properties)	Acer campestre 'Elegant'
SWALEDAL ROAD	o/s 46-44	Damaging	Extensive f/w damage, growing within c/w - no kerbstones	Platanus x hispanica	Plant in new 800mm o/s 42-44 (repositioned to between 2 properties)	Acer campestre 'Elegant'